



Excelsior Wind Farm: Environmental Incident Register

Date Updated:

Number	Status	Type of Incident	Contractors			
Incident / Non Compliance	OPEN	Spill				
		Fauna				
		Flora				
		CLOSED	Pollution			
			Incorrect storage			
			No mitigation			
			Illegal Dumping			
		HOLD	Poor Housekeeping			
			Unsafe practice			
Number	Status	Type of Incident	Contractor	Location of Incident on site	Description of Incident	
1	Closed					
2	Closed					
3	Closed	Spillage risk	Group Five	Site entrance gate		
4	Closed	Spillage risk	Group Five	Between internal road 5 - 7		
5	Closed	Spillage risk	Group Five	Alongside internal access road 6		
6	Closed	Animal rescue	Group Five	Alongside internal access road 1		
7	Closed	Spillage risk	MEV Energy	Substation area		
8	Closed	Spillage risk	Group Five	Site office laydown area		









